


COMPONENTS      FUNCTION      LOCATION      CONTACTS

1MC    MOTOR CONTACTOR      13      1,2,3

1DS    MOTOR PROTECTOR      1,2,3


1PS    PRESSURE SWITCH      18

1SW    HAND/OFF/AUTO SELECTOR SW.      13



**NOTES FOR FIELD WIRING:**

- 1) USE COPPER WIRING ONLY EXCEPT AT TERMINALS MARKED CU-AL,
- 2) TO REDUCE THE RISK OF FIRE, REPLACE WITH SAME TYPE AND RATING AS FUSE ORIGINALLY INSTALLED.

DRAWN	SR	3-1-95	 <b>METRON, INC.</b> DENVER, CO.
CHECK	x.d.	3-1-95	
APPD	M.	3-1-95	
SCHEMATIC, MODEL M15B, THREE PHASE WITH MOTOR PROTECTOR SWITCH JOCKEY PUMP CONTROLLER, W/O XFMR.			CS32273C SCALE N.T.S. SHEET 1 OF 1